#### UNCLASSIFIED

# AD NUMBER AD845032 **LIMITATION CHANGES** TO: Approved for public release; distribution is unlimited. FROM: Distribution: Further dissemination only as directed by Commanding General, HQ, USAMC, Attn: AMCPM-IRFO-T, Washington, DC, APR 1966, or higher DoD authority. AUTHORITY AVSCOM ltr 12 Nov 1973



An.

USATECOM PROJECT NO. 4-3-0100-17 USAAWITA PROJECT NO. 64-20

ENGINEERING TEST OF UH-1D HELICOPTER WITH XT67 POWER PLANT INSTALLED

FINAL REPORT


PROJECT ENGINEER

MITTIAM A. ANDERSON PROJECT PILOT

APRIL 1966

U. S. ARMY AVIATION TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

## DDG AVERTABETH SY NOTAGE

The transfer of the property o

### Reproduction Limitations

Reproduction of this desimant in whole or in part is prohibited except with primities on potential except with primities on potential distribution commanding denotes in the product with ANCPMATRICAL PROJECT Managers Weshington D. C. 1985 in the original produces the document for United States Government phyposes;

### uudablomintanistin,

Destroy this report when it is no longer needed. Do not return it to

## 

The findings in this report for not to be construct as an official Department of the Army Sport of unless so designated by other authorized documents (select and approved by the Department of Electric).

#### Trada Names

The did of Stade stripes in drive separate description constitute on a later separate description of the separate description of the distribution of the separate description of the separate descript

This document has be further distributed by appropriate making the species of the second of the seco

# USAAVNTA PROJECT NO. 4-3-0150-17 USAAVNTA PROJECT NO. 64-20

ENGINEERING TEST OF UH-1D HELICOPTER WITH XT67 POWER PLANT INSTALLED

TEST REPORT

JOHN R. MELTON PROJECT ENGINEER

WILLIAM A. ANDERSON PROJECT PILOT

**APRIL 1966** 

U. S. ARMY AVIATION TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA

This document may be further distributed by any holder only with specific prior approval obtained through Commanding General, Hq, USAMC, ATTN: AMCPM-IRFO-T, Project Manager, Washington, D. C.

TA	пı	г.	$\sim$		~	O N I	T	•	N I	TC	
TA	ВL	t.	U	-	u	JIN	1	t. I	W	15	

			Page
ABSTRACT	••••••		vi
FOREWORD	••••••	•••••••••••••••••••••••••••••••••••••••	viii
SECTION 1.	GENERA	L	
	1.1 1.2 1.3 1.4 1.5 1.6	Objectives Responsibilities Description Background Findings Conclusions Recommendations	i
SECTION 2.	DETAIL	S OF TEST	
	2.0 2.1	Introduction	
	2.1.1 2.1.2 2.1.3 2.2 2.3	HoverClimb	7 9 10 12
	2.3.1 2.3.2 2.3.3	Power Management Static Droop Static Load Sharing Transient Response Cockpit Engine Controls and Information	15 16 17
SECTION 3.	APPENI	Display	19
	II [	Test Data Description of XT67 Power Plant	59

#### ABSTRACT

This report presents the results of limited engineering tests conducted to determine the performance characteristics of the XT67 power plant (i.e. two T72 engines) installed in a YUH-1D/48-foot rotor helicopter. Ten productive hours were flown between 14 October 1965 and 22 October 1965. The tests were performed at the airframe contractor's flight test facility located at Greater Southwest Airport, near Fort Worth, Texas.

The U. S. Army Aviation Test Board (USAAVNTBD) was assigned as Executive Test Agency, responsible for coordinating the test plan preparation, executing the limited serviceability testing and coordinating the test reporting. The U. S. Army Aviation Test Activity (USAAVNTA) was assigned the responsibility for coordinating the planning and reporting of the engineering tests with USAAVNTBD and executing the engineering tests.

The XT67 power plant improved the hover and climb performance of the UH-1D/48-foot rotor helicopter by sustaining the helicopter main transmission torque limit to higher altitudes than were possible with the T53-L-11 engine. The XT67 power plant improved the level flight performance by allowing higher cruise speeds for essentially the same range. Increased range could be attained by shutting down one engine. Test installation losses were high but could be reduced significantly through continued development.

The static droop characteristics of the XT67 power plant were acceptable. Static load sharing was excellent; however, load sharing during power transient, although adequate, could be improved. The transient response of the power plant-dynamic system was slow. This shortcoming should be corrected prior to service test.




PHOTO NO. 1 XT67 POWER PLANT

#### 1. AUTHORITY

Letter, AMCPM-IR, Hq, U. S. Army Materiel Command (USAMC), 29 July 1963, subject: "Evaluation of Alternate Engine Installation in the UH-1D Helicopter," with 1st Indorsement, AMSTE-BG, Hq, U. S. Army Test and Evaluation Command (USATECOM), 28 August 1963.

#### 2. REFERENCES

- a. Letter, AMCPM-IR-T, Hq, USAMC, 8 July 1964, subject: "USATECOM Plan of Test, Project Number 4-3-0150-10, Evaluation of Alternate Engine Installation in the UH-1D Helicopter," Undated, with 1st Indorsement, AMSTE-BG, Hq, USATECOM, 20 August 1964.
- b. Engineering Plan of Test of the LTCIK-4 Engine Installed in the UH-1D Helicopter, USATECOM Project Number 4-3-0150-10, U. S. Army Aviation Test Activity (USAAVNTA), September 1964.
- c. Letter, STEBG-TPAC, U. S. Army Aviation Test Board (USAAVNTBD), 24 September 1964, subject: "Change to Evaluation of Alternate Engine Installation Plan of Test for UH-1D Helicopter, USATECOM Project Number 4-4-0150-10."
- d. Technical Manual TM 55-1520-210-10, "Operator's Manual Army Model UH-1D Helicopter," Department of the Army, 30 September 1964.
- e. Report FTC-TDR-64-27, "Category II Performance Tests of the YUH-1D with a 48-foot Rotor," U. S. Air Force Flight Test Center, November 1964 (AD 452710).
- f. Letter, STEAV-PO, USAAVNTA, 3 November 1964, subject: "Evaluation of the Alternate Engine Installation Using the T72 Engine Installed in the UH-1D, USATECOM Project Number 4-3-0150-10."
- g. Letter, AMCPM-IR-T, Hq. USAMC, 28 December 1964, subject: "USATECOM Plan of Test, Project Number 4-3-0150-10 Engineering Plan of Test of the LTCIK-4 Engine Installed in the UH 19 Helicopter," with 1st Indorsement AMSTE-BG, Hq. USATECOM, 13 January 1965.
- h. Plan of Test, USATECOM Project Number 50-10, "Evaluation of Alternate Engine Installation in the UH-1D Hell optor," USAAVNTBD. 31 March 1965.

- i. Engine Specification No. 2252-A, "XT67 Power Plant Aircraft Twin Turboshaft Engine Continental Model 217A-2," Continental Aviation and Engineering Corporation, 15 July 1965.
- j. Engine Specification, T53-L-11 Shaft Turbine Engine, Lycoming Division of AVCO Corporation.
- k. Letter, 81.JRG:im 1346, Bell Helicopter Company, 17 July 1965, subject: Proposed Instrumentation for Test of XT67-T-1 Installed in YUH-1D Helicopter with a 48-Foot Diameter Main Rotor.
- 1. Unclassified Message, SMOSM-EAA 10-1363, U. S. Army Aviation Materiel Command, 14 October 1965, subject: "Safety of Flight Release for Continental Power Plant Installation XT67."
- m. AF Technical Report No. 6273, "Flight Test Engineering Handbook," U. S. Air Force Flight Test Center, revised January 1966.




PHOTO NO. 2 - UH-1D WITH XT67 POWER PLANT INSTALLED

#### SECTION 1 - GENERAL

#### 1.1 OBJECTIVE

To conduct limited engineering tests to determine the performance characteristics of the XT67 power plant installed in the UH-1D helicopter.

#### 1.2 RESPONSIBILITIES

- 1.2.1 The USAAVNTBD was assigned as Executive Test Agency responsible for coordinating the test plan preparation, executing the limited service testing, and coordinating the test reporting.
- 1.2.2 The USAAVNTA was assigned responsibility for coordinating the planning and reporting of the engineering portion of the test with USAAVNTBD and executing this portion of the test.

#### 1.3 DESCRIPTION OF MATERIEL

See Section 3, Appendix II.

#### 1.4 BACKGROUND

- 1.4.1 The Army has a continuing requirement to attain the optimum potential for all equipment in the inventory. The ultimate usefulness of the UH-1D helicopter could be enhanced by an improvement in the hovering and climbing capabilities.
- 1.4.2 On 2 May 1963, the engine contractor submitted to the Iroquois Project Manager a proposal to install the XT67 in a UH-1D helicopter for evaluation as an alternate power plant. The engine manufacturer's test data indicated that the UH-1D's hovering capability, climb performance, acceleration, and/or throttle response would be improved with the alternate power package.
- 1.4.3 On 29 July 1963, the Iroquois Project Manager requested USATECOM to evaluate the XT67 power plant installation. USATECOM assigned the program to USAAVNTL on 28 August 1963. On 8 July 1964, the Iroquois Project Manager ested that USAAVNTA accomplish all engineering tests for this program. USATECOM, on 20 August 1964, assigned USAAVNTA as Participating gency with responsibilities as described in Paragraph 1.2.2. The scope of Tie program was enlarged to include limited performance testing of the XT67 power plant in the UH-1D helicopter. An additional requirement for testing at 9500 pounds gross weight was issued by USATECOM on 13 January 1965. A consolidated test plan incorporating the required changes was published by USAAVNTBD on 31 March 1965.

#### 1.5 FINDINGS

#### 1.5.1 GENERAL

The XTG7 offered many desirable characteristics as a power plant for the UH-ID helicopter. The airframe contractor had relatively little flight experience with the installation prior to this evaluation. The installation was not optimized or developed. With very little refinement, the performance and engine operating characteristics as described in this report could be significantly improved. The XT67 installation offered significant improvement in the performance of the UH-ID helicopter, particularly in the areas of hovering, climb and level flight. Although the single-engine height-velocity characteristics were not quantitatively evaluated, a significant safety factor over a single-engine helicopter was available.

#### 1.5.2 HOVER

Hovering performance was improved for all ambient conditions; however, the hot-day hovering capability improvement in the test installation was small. The hot-day hover performance could be greatly improved through alimination of the hot-day power-available limitation based on maximum allowable power turbine inlet temperature. In addition, the hot-day shaft horsepower (SHP) available, and thus the hot-day hover performance, could be greatly improved through elimination of the compressor air bleed used to drive cooling blowers in the test installation. The magnitude of the effect of eliminating the bleed could not be calculated because neither the amount of bleed nor its effect upon engine performance was known.

#### 1.5.3 CLIMB

An improvement in climb performance was realized because the transmission limit SHP could be maintained up to an altitude of 6600 feet on a standard day. Sea-level rates of climb were not improved, but a higher rate of climb was possible at higher altitudes.

#### 1.5.4 LEVEL FLIGHT

Level flight performance was improved, even though range was essentially unchanged, because of higher optimum cruise speeds. Optimum cruise speed was the placard limit airspeed in every case. Range was increased approximately 30 percent by shutting down one engine and cruising on the other; however, cruise speed was reduced 15 to 35 knots calibrated airspeed (KCAS). If the second engine was kept at flight-idle rather than shut down, the improvement in range was negligible.

#### 1.5.5 ENGINE OPERATING CHARACTERISTICS AND POWER MANAGEMENT

The static droop characteristics of the XT67 were satisfactory though not optimum. Static load sharing was excellent. No pilot attention was required to maintain equal torque between the two engines. Transient response of the power plant-dynamic system was slow and considered a shortcoming; however, at the time of this evaluation no attempt had been made to optimize this characteristic.

#### 1.5.6 COCKPIT ENGINE CONTROLS AND INFORMATION DISPLAY

The cockpit controls and instrumentation were adequate for the test installation. Many improvements should be incorporated in this area, however, prior to service test.

#### 1.6 CONCLUSIONS

- 1.6.1 The XT67 power plan. proved the hover performance of the YUH-1D/48-foot rotor helicopter at all ambient conditions in which maximum SHP available from the T53-L-11 engine was not limited by the main transmission. (Paragraph 2.1.1.4)
- 1.6.2 The XT67 power plant improved the climb performance of the YUH-1D/48-foot rotor helicopter by sustaining the helicopter main transmission torque limit to \$600 feet. The corresponding increase in power available resulted in higher rates of climb at higher altitudes. (Paragraph 2.1.2.4)
- 1.6.3 The maximum single-engine rate of climb (sea-level standard day) attained with a climb start gross weight of 7000 pounds was 820 feet per minute. Service ceiling at these conditions was 15,000 feet. (Paragraph 2.1.2.4.2)
- 1.6.4 The XT67 power plant improved the level flight performance of the YUH-1D/48-foot rotor helicopter by allowing higher cruise speeds for essentially the same range. (Paragraph 2.1.3.4)
- 1.6.5 By operating the XT67 power plant on a single engine with the second engine shut down, range was increased approximately 30 percent at those conditions in which level flight at single-engine normal rated power was possible. (Paragraph 2.1.3.4.3)
- 1.5.6 The power losses caused by the test installation were high and particularly detrimental to hot-day performance. (Paragraph 2.2.4)
- 1.6.7 The high test installation power losses could be reduced significantly through continued development. (Paragraph 2.2.4)

- 1.6.8 Static droop characteristics of the XT67 power plant were acceptable, although droop cam compensation was not optimum. (Paragraph 2.3.1.4)
- 1.6.9 Static load sharing was excellent. (Paragraph 2.3.2.4)
- 1.6.10 Transient response of the power plant-dynamic system was slow. (Paragraph 2.3.3.4)
- 1.6.11 Load sharing during power transients was adequate but could be improved. (Paragraph 2.3.3.4.3)
- 1.6.12 The engine cockpit controls and information display were adequate for the test installation. Changes should be incorporated, however, prior to service test. (Paragraph 2.3.4.4)
- 1.6.13 Engine failure and fuel control malfunction could be readily detected, identified, and compensated for; however, a modified engine torquemeter indicator and collective pitch position indicator would simplify detection, identification and compensation. (Paragraphs 2.3.4.4.4 and 2.3.4.4.5)

#### 1.7 RECOMMENDATIONS

1.7.1 Effort should be initiated by the contractors to correct the following shortcoming:

Inadequate transient response of the power plant-dynamic system. (Paragraph 2.3.3.4)

- 1.7.2 Developmental effort should be continued by the contractors to correct or improve the following items:
- a. Reduce the installation power losses, particularly those affecting hot-day SHP available. (Paragraph 2.2.4)
- b. Optimize the static droop characteristics of the power plant for increased compensation at high collective settings. (Paragraph 2.3.1.4.3)
- c. Improve the load sharing during power transients. (Paragraph 2.3.3.4.3)
- d. Provide better identification of the two modes of operation of the starter button. (Paragraph 2.3.4.4.1)

- e. Provide the individual twist-grips with individually adjustable friction. (Paragraph 2.3.4.4.2)
- f. Provide the twist-grips with a "dead band" at the full-open position to prevent the fuel control levers from "backing off." Paragraph 2.3.4.4.2)
- g. Make both twist-grips the same size and provide a distinctive texture for each to facilitate identification by feel. (Paragraph 2.3.4.4.2)
- h. Reduce the distance between the twist-grips and the flight-idle release buttons to reduce hand motion. (Paragraph 2.3.4.4.2)
- i. Indicate, on the large and small needles of the dual tachometer, rotor speed and power plant output shaft speed respectively.
- j. Provide a three-needle torque indicator, displaying leftengine torque, right-engine torque and total torque. (Paragraph 2.3.4.4.4)

#### SECTION 2 - DETAILS OF TEST

#### 2.0 INTRODUCTION

- 2.0.1 Except in climbing flight, no attempt was made during this evaluation to measure directly helicopter performance because the power required in most flight regimes for the YUH-1D/48-foot rotor helicopter was well defined in Reference e, Foreword. The significant parameters measured were the power available and fuel-flow characteristics of the XT67. Based on the results of these measurements, the performance of the YUH-1D/48-foot rotor helicopter with the XT67 installed could be calculated using the data contained in Reference e.
- 2.0.2 Climb performance was increased due to the increased power available and this performance characteristic was measured directly.
- 2.0.3 Due to the scope of this evaluation, several limitations were imposed and several assumptions were made. First, no attempt was made to gather information on the effect of engine output speed (rotor speed) upon engine performance. All data presented in this report was valid for a rotor speed of 324 rpm. Second, there was insufficient information available to determine the amount of compressor bleed air used in the test installation to drive cooling blowers. Additionally, the effect of compressor bleed on engine performance was not well established. Because of the ambiguity of the effect of bleed upon engine performance, no attempt was made to standardize the observed data to a zero-bleed condition. Third, the data presented in this report was based on the assumption that both engines of the XT67 power plant had specification torquemeters. Prior to this evaluation, the XT67 power plant was calibrated in a test cell. It, however, was not run in a single-engine configuration sufficiently to define the individual engine torquemeter pressure as a function of engine output torque. There was no dependable method of obtaining this information in the limited flight time available. Any deviation between the test engine torquemeters and the torquemeter characteristics in Engine Specification 2252-A (Reference i) affected the accuracy of the performance data contained in this report. Engine Specification No. 2252-A, Paragraph 3.23, states: "The torquemeter signals shall indicate the torque developed by the engines within the following tolerances:
- a. From maximum steady-state torque to normal rated output torque: ± 3 percent of the value being measured.
- b. From normal rated output torque to one-third of normal rated output torque: ± 3 percent of the value obtained at normal rated torque."

2.0.4 Engine handling characteristics and power management were briefly but quantitatively evaluated in terms of static droop and transient response in both the twin- and single-engine modes. Static load sharing and transient load sharing were briefly investigated. Cockpit engine controls and engine information display were briefly evaluated. Time did not allow evaluation of the single-engine height-velocity characteristics of the helicopter.

# 2.1 PERFORMANCE OF YUH-1D/48-FOOT ROTOR HELICOPTER WITH XT67 POWER PLANT INSTALLED

- 2.1.1 The hovering and level-flight performance characteristics presented in this report were calculated based upon the data presented in Reference e for power required in hovering and level flight.
- 2.1.2 The climb performance presented in this report was based upon actual flight test data obtained during climb performance tests.
- 2.1.3 All summary performance for the helicopter with the XT67 power plant installed was based upon observed installed engine characteristics which included the installation losses of the test helicopter.
- 2.1.4 The helicopter performance with the T53-L-11 engine was calculated for comparison purposes based upon fuel flow and power available obtained from an airframe contractor report. Fuel flow and shaft horsepower available from this report were based upon: a. Engine Mcdcl Specification T53-L-11 (Reference j); b. Compressor inlet total pressure loss = 0; c. Compressor inlet total temperature rise = 2 degrees Centigrade (C); d. Percent air bleed = 0.6 percent; and e. Power extracted from gas producer section = 0.

#### 2.1.1 HOVER

#### 2.1.1.1 Objective

The objective of the hover performance tests was to define the hover performance of the UH-lD/48-foot rotor helicopter with the XT67 power plant installed.

#### 2.1.1.2 <u>Method</u>

The shaft horsepower (SHP) required to hover at various gross weights, pressure altitudes and ambient temperatures was obtained from Reference e. The SHP available from the XT67 power plant was obtained from Figure 15, Section 3. Appendix I. Based upon these characteristics, the hover ceiling both in and out of ground effect was calculated for various gross weights and ambient temperatures.

#### 2.1.1.3 Results

The hover performance test results of the YUH-1D/48-foot rotor helicopter with the XT67 power plant installed are presented in Figures 1 and 2, Appendix I.

#### 2.1.1.4 Analysis

- 2.1.1.4.1 All hover performance was based upon military rated power for both the XT67 power plant and the T53-L-11 engine.
- 2.1.1.4.2 On a standard day, the out-of-ground effect (OGE) hover performance of the UH-1D/48-foot rotor helicopter was significantly better with the XT67 power plant than with the T53-L-11 engine. With the XT67 power plant, the OGE standard-day hover ceiling was 4000 feet at 9500 pounds gross weight. With the T53-L-11 engine, the maximum gross weight for OGE hover at sea level was 8850 pounds and at 4000 feet, 8430 pounds. At 8500 pounds gross weight, the OGE hover ceiling with the T53-L-11 was 3690 feet; the XT67 increased the OGE hover ceiling to 10,020 feet. Using only the right single engine of the XT67 power plant, the maximum gross weight for OGE hover at sea level was 6200 pounds.
- 2.1.1.4.3 The hot-day (35-degree-C) OGE hover performance of the YUH-1D/48-foot rotor helicopter was not as greatly improved with the installation of the XT67 power plant as was the standard-day performance. The reason was that the SHP available on a hot day from the XT67 power plant was low for reasons explained in Paragraph 2.2.4. Maximum gross weight for OGE hover on a 35-degree-C day at sea level was 8360 pounds with the XT67 power plant and 8160 pounds with the T53-L-11 engine. At design gross weight, 6600 pounds, the OGE hover ceiling was 6470 feet pressure altitude with the XT67 power plant and 5900 feet pressure altitude with the T53-L-11 engine.
- 2.1.1.4.4 The 2-foot skid height in-ground-effect (IGE) hover ceiling is presented in Figure 2, Appendix I. This hovering skid height was approximately the limit from which a satisfactory takeoff could be accomplished with this helicopter without contacting the ground or exceeding engine military power limits. The 2-foot nover ceiling at 9500 pounds gross weight on a standard day was 12,400 feet with the XT67 power plant and 5850 feet with the T53-L-11 engine.
- 2.1.1.4.5 Using only the right single engine of the XT67 power plant, the maximum gross weight for a 2-foot hover at sea level was 7420 pounds.

2.1.1.4.6 On a 35-degree-C day the 2-foot hover ceiling at 9500 pounds gross weight was 1080 feet pressure altitude with the XT67 power plant and 300 feet pressure altitude with the T53-L-II engine. Again there was only a small gain in hot-day hover performance due to the low hot-day SHP available from the XT67 power plant for reasons explained in Paragraph 2.2.4.

#### 2.1.2 CLIMB

#### 2.1.2.1 Objective

The objective of the climb performance tests was to define the climb performance of the YUH-1D/48-foot rotor helicopter with the XT67 power plant installed.

#### 2.1.2.2 Method

- 2.1.2.2.1 Continuous climb performance tests were conducted from minimum attainable altitude to service ceiling at military rated power. One climb was made at a climb-start gross weight of 9500 pounds using both left and right engines. One climb was made at a climb-start gross weight of 7000 pounds using only the left engine. One climb was made at a climb-start gross weight of 7000 pounds using only the right engine.
- 2.1.2.2.2 A rotor speed of 324 rpm was maintained during the climb tests. SHP was maintained at either the torque limit of the helicopter transmission or the maximum power available at the test conditions using the military power limits.
- 2.1.2.2.3 The climb performance data was corrected to standard-day conditions and standard climb gross weights of 9500 pounds for the twinengine climb and 7000 pounds for the single-engine climbs.

#### 2.1.2.3 Results

The results of the climb performance tests are presented in Figures 3. 4 and 5. Appendix I.

#### 2.1.2.4 Analysis

2.1.2.4.1 The climb performance of the YUH-1D/48-foot rotor helicopter was improved by the installation of the XT67 power plant. The sea-level rate of climb was not significantly changed due to the fact that the maximum power available was limited to the torque limit of the main transmission. No flight test climb performance data was available for

the T53-L-11 engine; however, sea-level rate of climb at 9500 pounds gross weight was 1560 feet/minute with both the XT67 power plant and the T53-L-9 engine. The increase in climb performance was the result of the capability of the XT67 to maintain the transmission limit power to a higher altitude, with a subsequent increase in power available above the altitude where the main transmission no longer limited maximum power (6600 feet). A higher service ceiling also resulted with the XT67 power plant. The time to climb to 10,000 feet, which was 9.3 minutes with the T53-L-9, was reduced 19.4 percent to 7.5 minutes with the XT67. Service ceiling at 9500 pounds climb-start gross weight was 14,630 feet with the XT67 power plant and 12,550 feet with the T53-L-9 engine.

2.1.2.4.2 With a sea-level climb-start gross weight of 7000 pounds, using only the left engine of the XT67 power plant, the sea-level rate of climb was 660 feet/minute and the service ceiling was 12,680 feet. At the same conditions using only the right single engine, the sea-level rate of climb was 820 feet/minute and the service ceiling was 15,000 feet, because of the higher SHP available.

#### 2.1.3 LEVEL FLIGHT

#### 2.1.3.1 Objective

The objective of the level-flight performance tests was to define the level-flight performance of the YUH-1D/48-foot rotor helicopter with the XT67 power plant installed.

#### 2.1.3.2 Method

The SHP required to maintain level flight with the YUH-1D/48-foot rotor helicopter was defined in Reference e. The curves of SHP required versus true airspeed presented in Figures 8 through 13, Appendix I were obtained directly from Reference e. SHP available and the fuel flow at any SHP for the XT67 were measured during this program as described in Paragraph 2.2. With this information the level flight performance of the YUH-1D/48-foot rotor helicopter was calculated for both single-engine and twin-engine XT67 operation.

#### 2.1.3.3 Results

The results of the level flight performance tests are presented in Figures 6 through 14, Appendix I.

#### 2.1.3.4 Analysis

2.1.3.4.1 The range rformance of the YUH-1D/48-foot rotor helicopter with the XT67 power plant was very similar to that with the T53-L-11

engine. A comparison in terms of range factor is shown in Figure 6, Appendix I. At low values of thrust coefficient ( $C_T$ ), less than .00294, the T53-L-11 showed slightly higher range performance than the XT67. At higher values of  $C_T$ , the range performance of the XT67 power plant was slightly superior. The "crossover"  $C_T$  of .00294 corresponded to approximately 8380 pounds gross weight at sea level or 7220 pounds gross weight at 5000 feet with a rotor speed of 324 rpm on a standard day.

- 2.1.3.4.2 The airspeed for maximum range with the XT67 power plant was always greater than or equal to the airspeed for maximum range with the T53-L-11. Recommended cruise speed for maximum range with the XT67 was the placard limit airspeed for all conditions. Recommended cruise speed with the T53-L-11 was the airspeed at .99 maximum nautical air miles per pound of fuel (.99 max NAMPP). With the T53-L-11, .99 max NAMPP occurred at or below placard limit airspeed. In general, the YUH-1D/48-foot rotor helicopter traveled approximately the same distance with the XT67 power plant as with the T53-L-11 engine; it would arrive sooner, however, with the XT67 nower plant installed.
- 2.1.3.4.3 There was a considerable increase in range to be gained by cruising on a single engine of the XT67 power plant with the second engine shut down. Range was increased approximately 30 percent in this manner; however, the decrease in cruise speed necessary to gain this increase in range was 15 to 35 knots true airspeed (KTAS) depending upon the combination of gross weight and altitude as shown in Figure 6, Section 3, Appendix I. The airspeed for maximum single-engine range was the airspeed at maximum continuous power available (normal rated power limit).
- 2.1.3.4.4 If the second engine of the XT67 power plant was operated at flight-idle instead of shut down to maintain twin-engine reliability, the range advantage was lost. The 15-to-35-KTAS cruise speed sacrifice, however, still resulted. The flight-idle fuel consumption of the second engine canceled the advantage of operating a single engine in its high-power, low-specific-fuel-consumption range.
- 2.1.3.4.5 Single-engine level flight was not possible for all conditions of gross weight and density altitude. The single-engine absorbe ceiling of the YUH-1D/48-foot rotor helicopter with the XT67 power plant is shown in Figure 7, Appendix I. The curve of this figure, based upon normal rated power on a standard day at a rotor speed of 324 rpm, shows the maximum altitude at which the helicopter was capable of level flight at the airspeed for minimum power required. At 8500 pounds gross weight, level flight could be maintained on one engine at normal rated power at a standard-day altitude of 5200 feet.

2.1.3.4.6 A calculated range mission is presented in Figure 14, Appendix I. This figure shows a comparison of range performance of the YUH-1D/48-foot otor helicopter with the T53-L-11 engine, XT67 power plant, XT67 right single engine with the second engine shut down, and XT67 right single ingine with the second engine at flight-idle. The conditions chosen for the comparative range mission, listed in Figure 14, Appendix I, were chosen as being typically representative, rather than nurposely favoring a particular power plant. The results of the comparative range mission are summarized in table on the following page.

#### 2.2 POWER AVAILABLE AND FUEL FLOW

#### 2.2.1 OBJECTIVE

The objective of the power-available and fuel-flow tests was to define through flight test data the parameters required to calculate maximum SHP available from the XT67 power plant and the fuel flow at any conditions of SHP pressure altitude and ambient temperature.

#### 2.2.2 METHOD

During stabilized flight all pertinent engine parameters, including SHP, fuel flow ( $W_f$ ), gas producer speed ( $N_1$ ), and power turbine inlet temperature ( $T_{T6}$ ) were recorded. By means of standard engineering methods (Reference m), these readings were reduced to standard-day, sealevel, static conditions, resulting in a single curve expressing the relationship of any two parameters for a single engine on a "referred" basis. These referred engine characteristics for both the left and right engines of the XT67 power plant are presented in Figures 20 through 22 and 25 through 27, Appendix I. With these referred characteristics, it was possible to calculate at any pressure altitude, ambient temperature, and airspeed, the SHP at any  $N_1$  or  $T_{T6}$ . Then, by knowing the maximum  $N_1$  available, as defined in Figures 19 and 24, and the maximum  $T_{T6}$  allowable as given in Engine Model Specification No. 2252A(Reference i), the SHP available could be calculated. In a similar fashion, the  $W_f$  required for any available SHP at any pressure altitude, ambient temperature or airspeed could be calculated.

#### 2.2.3 RESULTS

The results of the power-available and fuel-flow tests are presented in Figures 15 through 27, Appendix I.

#### 2.2.4 ANALYSIS

2.2.4.1 Due to the limited scope of this test, no effort was made to determine the effect of engine output shaft speed (rotor speed) upon

RESULTS OF THE COMPARATIVE RANGE MISSION

Configuration	Nautical Air Miles Traveled	Elapsed Time For Maximum Nautical Air Miles Traveled hr	Elapsed Time For 200 Nautical Air Miles hr	Average Cruise Airspeed KTAS
XT67 Power Plant	230	2,064	1.815	111,4
T53-L-11 Engine	235.7	2.227	1,900	105.8
XT67 Right Single Engine with Left Engine Shut Down	306.3	3,538	2.36	86.6
XT67 Right Single Engine with Left Engine at Flight-Idle	209.5	2,445	2.36	85,7

engine performance. All data presented in this report, therefore, was for an engine output shaft speed of 6600 rpm (324 rpm rotor speed). The data for the referred engine characteristics was not corrected for non-optimum power turbine speed. Similarly, the effects of compressor air bleed and power extracted from the gas producer section were not defined and no bleed correction was made. The data presented in the referred engine characteristics curves, therefore, reflects the performance of the XT67 power plant as installed in the test helicopter with all the installation losses included with the exception of compressor inlet duct losses.

- 2.2.4.2 The maximum SHP available at military power limits was limited either by maximum allowable  $T_{T_6}$ , 677 degrees C, or by maximum N1 available ("topping" N1) as limited by the fuel control. As a general rule, power was limited by "topping" N1 on a standard day or cooler and by maximum  $T_{T_6}$  on a hotter than standard day.
- 2.2.4.3 Although the exact effect of bleed air upon a single engine of the XT67 power plant was not known quantitatively, its general effect was to raise the  $T_{T6}$  for a given SHP. This effect was greater at high ambient temperatures than at low ambient temperatures. This meant that, with bleed air being extracted, not only would the SHP available at  $T_{T6}$  limit be lowered, but the ambient temperature range over which SHP available was limited by maximum  $T_{T6}$  would be extended to lower ambient temperatures for any pressure altitude. The fact that maximum SHP available was limited by maximum  $T_{T6}$  at high ambient temperatures was of particular significance with the XT67 power plant. The power plant should be configured to be limited by "topping"  $N_{1}$  over as large a span of ambient temperatures as possible.
- 2.2.4.4 With a twin-engine installation, the two engines are never precisely matched. There is always a relatively "strong" and a relatively "weak" engine. Likewise, the static droop characteristics are not the same. To overcome this, the XT67 power plant employed a torque matching device which "beeped up" the low engine, or shifted its static droop line to the point where the engine torquemeter output pressures would be equal at any load or rotor speed.
- 2.2.4.5 When increasing power was demanded by increasing collective pitch, the engine supplied an equal torque to the rotor until the "weak" engine reached its maximum output, limited by either "topping" N $_1$  or maximum  $T_6$ . If the "weak" engine was limited by "topping" N $_1$ , a further increase in collective pitch resulted in the "weak" engine's continuing to put out an essentially constant power. The "strong" engine then continued to increase its power output until the limit of the "strong" engine was reached.

- 2.2.4.6 On the other hand, if the "weak" engine was limited by maximum  $T_{T_6}$ , a further increase in load resulted in the torque matching device's "be-ping" the "weak" engine into an unacceptable overtemp condition in ar effort to match torque output.
- 2.2.4.7 The effect was that when the "weak" engine was limited by "topping"  $N_1$  the SHP available from the XT67 power plant was the total of the SHP available from the left engine and the SHP available from the right engine. When the "weak" engine was limited by maximum allowable  $T_{T_6}$ , the SHP available from the XT67 power plant was limited to twice that available from the "weak" engine. An example of the conditions in which the weak engine was limited by maximum  $T_{T_6}$  may be seen in Figures 15 through 17, Appendix I. At 5000-foot pressure altitude and +35-degree-C ambient temperature, SHP available from the left engine was 393 and SHP available from the right engine was 423. The combined SHP available from the XT67 power plant was 786, twice that available from the "weak" left engine. The 30 SHP remaining in the right engine was not available without either overtemping the left engine. This took the "weak" engine governor off line and allowed the twist-grip selection of maximum power on that engine while collective pitch was increased to absorb remaining power on the right engine.

#### 2.3 ENGINE OPERATING CHARACTERISTICS AND POWER MANAGEMENT

#### 2.3.1 STATIC DROOP

#### 2,3.1.1 Objective

The objective of the static droop tests was to define the static droop characteristics of the XT67 power plant in both the twin-engine and single-engine configurations.

#### 2.3.1.2 Method

Rotor speed was established on the ground prior to the static droop tests at 324 rpm. The power turbine speed select (beep) switch setting was not changed for the remainder of the test at two airspeeds and the power demand was increased in increments by increasing collective pitch. The resulting relationship between engine output torque and rotor speed was recorded.

#### 2.3.1.3 Results

The results of the twin-engine and single-engine XT67 static droop tests are presented in Ffgures 28 and 29, Appendix I.

#### 2.3.1.4 Analysis

- 2.3.1.4.1 The test installation had a collective "compensator cam" installed, so the basic governor droop was not evaluated. The compensated droop for both single- and twin-engine operation was adequate but not optimum. Figure 28, Appendix I shows that with both engines operating during a vertical takeoff and climb the rotor speed stayed constant to within 2 rpm without beep adjustment. Slight over-compensation of droop occurred in the mid power range. This is a desirable feature in vertical flight since it helps maintain a high rotor speed as a safety margin and aids in preventing rotor overspeed during power reduction during a landing.
- 2.3.1.4.2 At 72 knots calibrated airspeed (KCAS), when the collective pitch settings for a constant power were higher than at zero airspeed, compensation was less ideal. Total static droop from a "needles-joined" to maximum power was approximately 5 rpm. This value was certainly acceptable; however, hysteresis of approximately 2 rpm made the apparent static droop appear somewhat larger.
- 2.3.i.4.3 The single-engine static droop is shown in Figure 29, Appendix I. As would be expected, static droop of the single engine was approximately double that of the twin engine. An increase in compensation at higher collective settings not only improved the single-engine static droop characteristics, but also improved the high-speed (and high-altitude) twin-engine static droop characteristics. At torque outputs greater than approximately 350 pounds-foot, the static droop characteristics of the left and right engines were not matched. A single compensator cam was fitted, so this mismatch was the result of the different fuel control characteristics of the two engines.

#### 2.3.2 STATIC LOAD SHARING

#### 2.3.2.1 Objective

The objective of the static load sharing tests was to determine the static load sharing characteristics of the two engines of the XT67 power plant.

#### 2.3.2.2 Method

At minimum collective pitch on the ground, a stabilized rotor speed was selected. The power demand was increased by increasing collective pitch in increments, allowing the engines to stabilize, then recording the individual engine output torques.

#### 2.3.2.3 Results

The results of the static load sharing tests are presented in Figure 30, Appendix I.

#### 2.3.2.4 Analysis

- 2.3.2.4.1 The static load sharing of the XT67 power plant was better than that of any other helicopter twin-engine installation tested to date. Differences in torquemeter readings were generally small enough to be unreadable on the standard instruments and well within their accuracy. Only at maximum torque output, when one engine was "topped" and could deliver no more power, was there any significant deviation from ideal static load sharing.
- 2.3.2.4.2 It should be noted that the torque matching device adjusts the relative power of the engines to match the torquemeter output hydraulic pressure. It does not actually match torque. If the torquemeter of one engine were to transmit a higher hydraulic pressure for a given torque output, that engine would produce less torque when the torque matching device was satisfied that the load was being equally shared by the engines. The load sharing characteristics of the XT67 power plant were only as accurate, reliable, and repeatable as the torquemeters of the individual engines. Without the automatic torque matching device of the XT67 power plant, the load sharing characteristics of these engines would probably have been poor. A high degree of pilot attention would have been required to keep the power output of the engines equal.
- 2.3.2.4.3 The single-engine static droop characteristics of the test installation were described in Paragraph 2.3.1.4. The single-engine static droop characteristics of the left and right engines were not well matched, especially at high torque output.

#### 2.3.3 TRANSIENT RESPONSE

#### 2.3.3.1 <u>Objective</u>

The objective of the transient response tests was to determine quantitatively the response of the XT67 power plant-dynamic system to abrupt power changes.

#### 2.3.3.2 Method

2.3.3.2.1 The helicopter was loaded to normal mission gross weight, 8500 pounds. At the test altitude, approximately 1900 feet pressure altitude, 85 percent military rated power was selected at approximately

- 67 KCAS and the collective nosition noted. The collective was then lowered to a stabilized autorotation in which the needles were just joined at a rotor speed of approximately 332 rom. Collective pitch was then increased at varying rates to the setting previously noted. Photo panel records were taken of the resulting transient response to the demands.
- 2.3.3.2.2 Single-engine transient response was also briefly evaluated, first as described above, then by recording the reaction of one engine as it assumed the load imposed when the second engine was "chopped" simulating a single-engine power failure.

#### 2.3.3.3 Results

The results of the transient response tests are presented in Figures 31 through 36, Appendix I.

#### 2.3.3.4 Analysis

- 2.3.3.4.1 Oscillograph recording of transient response data was not available, so a detailed analysis of the XT67 power plant's transient response, including system lags and time constants, could not be made. The results obtained through photo panel recording presented here are, however, representative of the results that could have been obtained more accurately through the use of an oscillograph.
- 2.3.3.4.2 Twin-engine transient response was poor and considered a shortcoming. The minimum allowable power-on rotor speed of 299 rpm was reached during torque demand rates of approximately 211 pounds-foot/second. With the T53-L-11 engine installed, this minimum transient droop was not reached at torque demand rates of 289 pounds-foot/second at approximately the same ambient conditions. Maximum XT67 gas-producer accelerations were approximately 5 percent/second. The engine acceleration, although slow, was very uniform. Torque changes were uniform and easily anticipated with directional control to avoid helicopter vawing. The engine manufacturer stated that acceleration could be easily increased through fuel control adjustments and that acceleration was purposely kept to a low value in the experimental installation to provide a highly damped torsionally stable dynamic system.
- 2.3.3.4.3 The load sharing during transient power demands was inferior to the static load sharing. The torque-matching device incorporated a variable damper which was set for very high damping to avoid any possible engine instability or hunting. There was room for considerable improvement in the test installation in the transient load sharing area. The difference in torque between the left and right engines during transient response reached as high as 72 pounds-foot, or approximately 20 percent.

2.3.3.4.4 The simulated single-engine power failure presented in Figure 36, Appendix I shows the only evidence of engine instability observed during the evaluation. Three oscillations in torque were observed while the right engine was accelerating to assume the load of the "chopped" engine. Although the peak oscillation was approximately 18 percent of the mean torque, this oscillation was not objectionable or even noted in flight. It should be noted that if a single-engine failure were to occur at a high combined power plant output power setting on a cold day at low pressure altitude, the operating engine would accelerate and exceed its limit torque if collective pitch were not lowered. For example, a left-engine failure at a combined power plant output of 800 SHP at sea level on a -10-degree-C day would result in a right-engine overtorque if corrective action were not taken by the pilot.

#### 2.3.4 COCKPIT ENGINE CONTROLS AND INFORMATION DISPLAY

#### 2.3.4.1 Objective

The objective of the cockpit engine controls and information display evaluation was to present specific comments concerning this aspect of the test installation.

#### 2.3.4.2 Method

This evaluation is based upon the comments of an experienced engineering test pilot.

#### 2.3.4.3 Results

The results of this evaluation are presented and discussed in Paragraph 2.3.4.4.

#### 2.3.4.4 Analysis

- 2.3.4.4.1 The two-position starter button on the cyclic control stick was satisfactory, but better identification of the two modes of operation seemed desirable. During air starts, it was easy to release the button fully; this took the starter motor off the line and resulted in a hot start.
- 2.3.4.4.2 The tandem twist-grip arrangement should be improved by incorporating the following changes:
- a. Provide the individual twist-grips with individually adjustable friction.
- b. Incorporate a "dead band" at the full-open position to prevent the fuel control levers from "backing off."

- c. Make both twist-grips the same size and provide a distinctive texture for each to facilitate identification by feel.
- d. Reduce, if possible, the distance between the twist-grips and the flight-idle release buttons to reduce hand motion.
- 2.3.4.4.3 The practice of displaying the power turbine speed ( $N_2$ ) on the large needle and rotor speed ( $N_R$ ) on the small needle of the dual tachometer is undesirable. Rotor speed is the primary parameter and should be displayed more prominently. The small needle is difficult to read and subject to considerable parallax. The pilot is not normally interested in  $N_2$  except for monitoring during needle-split operation.
- 2.3.4.4.4 A three-needle torque indicator displaying left-engine torque, right-engine torque and total power plant torque is desirable. The total torque indication is desirable because over a large range of altitude and ambient temperature conditions the power output of the XT67 power plant is limited by helicopter main transmission torque limit. With a separate indicator for each engine, the total torque must be summed by a pilot. Having individual left- and right-engine output torque on one indicator would aid the pilot in identifying an engine failure or torque matching device malfunction.
- 2.3.4.4.5 The fuel control incorporated a manual mode by which fuel flow to the engine could be regulated directly by twist-grip rotation. This manual mode would restore full power should a fuel control malfunction restrict fuel flow to either engine. A fuel control failure resulting in a reduction in fuel flow could be identified by the decrease in rotor speed due to single-engine static droop and the reduction of torque on one engine. The recommended three-needle torque indicator would simplify identification of the failed engine. Were a fuel control failure to result in an increase in fuel flow to either engine, this could be identified by an increase in rotor speed and an acrease in torque on the engine with the malfunctioning system. Again, the recommended torque indicator would simplify identification of the malfunctioning engine.




PHOTO NO. 3 and 4 - UH-1D COCKPIT DISPLAY and THROTTLE CONTROL STICK 20

SECTION 3 - APPENDICES

APPENDIX I

TEST DATA

# FIGURE NO. 1 HOVERING CEILING OUT OF GROUND EFFECT YUH-ID | 48 FOOT ROTOR USA S/N 60-6030 XT-67 POWERPLANT S/N 2 MILITARY RATED POWER ROTOR SPEED = 324 RPM

#### NOTES:

- I. SHAFT HORSEPOWER NEQUIRED TO HOVER OUT OF GROUND EFFECT OBTAINED FROM FTC-TDR-64-27
- E SHAFT HARSEPOWER AVAILABLE, XT-67, FROM FIGURES NO 15 AND 17.
- 3. SHAFT HORSEPOWER AVAILABLE, T-53-L-11, FROM BHC. RPT. 205-099-705







FIGURE NO. 2
FOURING CEILING IN GROUND EFFECT
YUH-ID/48 FOOT ROTOR USA %, 60-6030
XT-67 POWERPLANT %/N 2
MILITARY RATED ROWER
ROTOR SPEED = 324 RPM
2 FOOT SNID NEIGHT


#### NOTES:

- I SHAFT HORSEPOWER REQUIRED TO HOVER WITH A 2 FOOT SKILL
- 2. SHAFT HORSEPOWER AVAILABLE, XT-67 FROM FIGURES NO 15 AND 17.
- 3. SHAFT HORSEPOWER AVAILABLE, T-53-1-11, FROM BHE RPT 205-079-705










# FIGURE NO 6 LEVEL FLIGHT RANGE SUMMARY YUH-ID/48 FOOT ROTOR USA 5/1 60-6030 XT-67 POWERPLANT 5/N 2 ROTOR SPEED = 324 PPM

- 1. DERIVED FROM FIGURES NO 8 THROUGH 13 .
- 2. RECOMMENDED CRUISE SPEED WITH XT-67 ENGINES BOTH OPERATING WAS PLACARD LIMIT AIRSPEED.
- 3 RECOMMENDED CRUISE SPEED WITH XT-67 RIGHT ENGINE ONLY OPERATING WAS THE AIRSPEED AT NORMAL RATED POWER.
- 4. FUEL FLOW DATA FOR T-53-L-II OBTAINED FROM BHC RPT 205-009-705






FIGURE NO. 8

LEVEL FLIGHT PERFORMANCE

YUH-ID / 48 FOOT ROTOR USA YN 60-6030

XT-67 POWERPLANT S/N 2


GROSS WEIGHT = 6270 LBS


DENSITY ALTITUDE = SEA LEVEL


ROTOR SPEED = 324 RPM


CG = 136.5 INCHES (MID)


CT = .002209


















FIGURE NO. 14  LCULATED RANGE MISSION  1. CULATED RANGE MISSION  XT-67 POWERPLANT SN 2  XT-67 POWERPLANT SN 2  S WEIGHT = 8500 LBS WITH FULL FUEL  5 WEIGHT = 8500 LBS WITH FULL FUEL	CRUISE SPEED WITHLE	eno specific Rivo	PONERPLANT	T-53-1-11 ENGINE XT-67 RIGHT SINGLE ENGINE WITH XT-67 RIGHT SINGLE ENGINE WITH	XT-67. 250 NAWT	XT-67 RIGHT ENGINE LES AT FEIGHT ID	20 22 26 26 28 30	TIME - HOURS
CA FUH-12 FNOWE START GROS	CRUISE AT RECOMMENDED  CRUISE ALTITUDE = SEA LI STANDARD DAY  STANDARD SAM RPH				<b>1</b> 3			



TIGURE S

WHAT I FTORS PONER AVAILABLE

YUH-10 | 48 FOOT ROTOR USA SIN 60-6030

XT-67 POWERPLANT SIN 2

MILITARY FOWER LIMITS

EERO AIRSPEED

NOTE

DERIVED FROM FIGURES NO 18 THROUGH







FIGURE NO. 16 LEFT ENGINE SHAFT HORSEPOWER AVAILABLE YUH-ID/ 48 FOOT ROTOR USA SIN 60-6030 KT-67 POWERPLANT - YN 2 LEFT ENGINE S/N X-6 MILITARY POWER LIMITS RERO AIRSPEED











#### NOTES:

15,000





- 3 MAXIMUM N. AVAILABLE VARRIES AS SHOWN IN FIGURE NO 24.
- 4 SHAFT HORSEPOWER DETERMINED FROM CURVE OF SHP/SVE VS N, NE (FIGURE NO 25) OR SHP/SVE





FIGURE NO 18


LEFT ENGINE INLET CHARACTERISTICS

YUH-ID/48 FOOT ROTOR USA 5/N 50-6030

XT-67 POWERPLANT 5/N 2

LEFT ENGINE 5/N X-6





CALIBRATED AIRSPEED ~ KNOTS




FIGURE No. 20

LEFT ENGINE CHARACTERISTICS

YUH-ID/48 FOOT ROTOR USA SN 60-6030

XT-67 POWERPLANT SN 2

LEFT ENGINE SN X-6

- 1. S AND TO BASED UPON MEASURED COMPRESSOR INLET TOTAL PRESSURE AND TEMPERATURE.
- 2. 100 % N. = 40,100 RPM
- 3. SHP BASED UPON SPECIFICATION RELATIONSHIP BETWEEN TORQUEMETER PRESSURE AND ENGINE OUTPUT SHAFT TORQUE.







FIGURE NO. 21
LEFT ENGINE CHARACTERISTICS
YUN-10/48FOOT ROTOR USA 34 60-6000
XT-6% POWERPLANT SIN Z
LEFT ENGINE SIN X-6


- I & AND & BASED UPON MEASURED COMPRESSOR
- 2. SHP BASED UPON SPECIFICATION RELATIONSHIP BETWEEN TORQUEMETER PRESSURE AND ENSINE OUTPUT SHAFT TORQUE.






- I. & AND VE BASED UPON MEASURED COMPRESSOR
- 2 SHP BASED UPON SPECIFICATION RELATIONSHIP BETWEEN TORQUEMETER PRESSURE AND ENGINE OUTPUT SNAFT TORQUE.





# FIGURE NO 24 RIGHT ENGINE VARIATION OF MAXIMUM GAS PRODUCER SPEED AVAILABLE YUH-ID 148 FOOT ROTOR USA SIN 60-6030 XT-67 POWERPLANT SIN 2 RIGHT ENGINE SIN X-5



FINDRY 180 25

RIGHT CHGINE CHARACTERISTICS


YUN-IN/48FOOT ROTOR USA 5N 60 6070


XT-67 POWERPLANT SIN 2

RIGHT EXCINE SIN X-5

#### HOTES

- 1. S AND TO BASEL UPON MEASURED COMPRESSOR INLET TOTAL PRESSURE AND TEMPERATURE
- 2 100 % N, = 40, 100 RPM
- 3 SHP BASED UPON SPECIFICATION RELATIONSHIP BETWEEN TORQUEMETER PRESSURE AND ENGINE OUTPUT SHAFT TORQUE.





p. 41. A COME CHARACTORISTICS Figure of the AVG Hispital Charles Himprode ... And From Forom USA 8% 60-6030 XT-67 FOWERFLANT S/N 2 1 - L' ENGINE SIN NOTES: COMPRESSOR I MAN O MYSOD WOON MEASURED THE TOTAL PRESSURE AND TEMPARATURE SPECIFICATION PELATIONS TORQUEMETER FRESSWAE SHAFT TORQUE. ... AGO 350 360 ر) الراش TEST STAND 300 CALIBRATION 280 260 20 220 200 L 100 200 ascord 500 HORSEPOWER - SHP/STE

ZERO AIRSPEED

PRESSURE ALTITUDE = 240 FEET

FREE AIR TEMPERATURE = 14 °C

COLLECTIVE COMPENSATOR

CAM: INSTALLED


CALIBRATED AIRSPEED = 72 KNOTS

PRESSURE ALTITUDE = 3100 FEET


FREE AIR TEMPERATURE = 18 °C


COLLECTIVE COMPENSATOR


CAM INSTALLED





500 5 0 5 5 0 5030




















# 

The (T61 namer) and be rested of two T72 gas turbine engines joined in a single now.

Tables, extracted not know ere to showing the performance ratings of the STAT power heart at larged sea-level static conditions and the engine operatory and the engine ope

The combining get was instead the torque output of the two engines and reduced the notational speed of the power turbines from 32,400 rpm at 100 percent N2 to a cover plant obtaint shall negative the same as that of the T53-L-11 engine, so in changes were received in the standard UH-1 main transmission. The power frain for each open forces the combining gearbox had a torquemeter as inverse to the first the combining gearbox had a torquemeter as inverse to the first the axial thrust from a helical idler gear in the relationship of the axial thrust from a helical idler gear is the relationship ensure output torque, so the oil pressure required to the axial thrust on the idler gear was discompositional enrine output torque, so the oil pressure required to the axial thrust was also proportional to torque and was instead on a system consistency gage. The overrunning clutch, also in the reduction near train of each engine, allowed transmission of torque in only one discation, providing single-engine operation either at pilot's selection or to case if a single-engine failure.

Each engine of the 7 bicrosor plant was a free turbine turboshaft engine, with a militar, where above invite limit) rating of 700 SHP. The gas generated as it is a major fries, incated aft of the combining gearbox, but a topological and or a standard fries, incated aft of the combining gearbox, but a topological and or a standard conference advantage in resistance to remain advantage, radh axial compressor rotor had only sever wiver-or, but a conference resistance of the engine to damage from social object, and the engine contractor and susceptibility to sand erosion and power deterioration in dust environment should prove to the relatively low. A two-stage axial flow turbine was compact and of a design as ilse to that of other engines produced by the engine contractor. Compressor discharge airflow entered the combustor through three air but the combustor chamber, providing combustor discharge cooling. Furthers are the desired combustion pattern. One of these airpaths passed over the combustor chamber, providing combustor discharge cooling. Furthers need. The sower turbine was a single-stage axial turbine coupled, through a shart concentric to the gas producer shaft, to the combining spearbox.

60

PERFORMANCE RATINGS OF THE MIGT POWER PLANT AT STANDARD SEA-LEVEL STAIL CONDITIONS

		מייי מעסייים די		A MINIOUND STREET STOLE CONDITIONS		
Ratings	Shaft Horsepower	Gas Ganerator rpm(max)	Output Shaft rpm	Fuel Consumption 1b/h-hr (max)	Rated Output Torque lb-ft	Power Turbine Inlet Temperature °F (max)
Maximum (30 min)	1400	39,250	6600	0.57	1113	1220
Normal	1200	38,360	0099	0.59	955	11511
90% Normal	1080	37,830	9600	0.61	360	114
75% Normal	006	36,350	6500	0.65	91.	1055
Flight-idle	0	27,500	9099	330 lb/hr		
Ground-idle	C	19,600	3640	190 15/hr	1	

ENGINE OPERATING LIMITS

Maximum       1200       1250         Normal       1113       1220         Max Transient       1300       1750		Torque 16-ft	Power Turbine Inlet Temperature
1113	haximum (פר חיות)	1200	1250
1300	Normal	1113	1220
	Mex Transient	1300	0521

Ine fuel control was hydromechanically operated. It provided control for engine-start fuel netering, engine-acceleration scheduling, gas-producer-speed governing and nower-lumbine-speed governing. A manual or "open loop" control system was also provided. Three control levers were provided for each fuel control. The gas generator condition lever determined the set point of the gas generator governor. Any setting less than fully open would lower the maximum fuel flow, or "topping" of the engine. This lever was connected directly to the pilot's twist-grip. The power turbine speed set lever determined the power turbine speed about which the engine would govern. A two-position switch placed the engine under enther automatic or manual mode, when the manual mode was selected, fiel flow to the engine was regulated directly by rotation of the pilot's twist-grip.

A hydro-mechanical torque matching device was used to maintain equal output torque for each engine. Addraulic pressure from each engine torquemeter was applied across a load sharing piston. Any imbalance in torquemeter pressure would cause the lead sharing piston to slew. Through a mechanical linkage this would cause engine with low torquemeter pressure to increase torque output. The linkage was designed so that the torque output of the high engine would not be reduced. The torque output of the low engine was increased by changing the power turbine speed set lever position. When output torquemeter pressure of the low engine was increased to the point where it was equal to that of the other engine, the pressure differential across the load sharing histon would go to zero and the histon would center in a trimmed condition. The sensitivity and response of the torque matching device could be varied through changing hydraulic orifice sizes.

During preliminary flight test of the XT67 power plant in the YUH-1D/48-foot rotor helicopter, it was found that additional cooling of the engine and combining gearbox lubricants was required. Heat exchangers and blowers were nestable in the test nelicopter. For convenience in installation, the cooling blowers were powered by air turbine motors nowered by high pressure engine compressor discharge bleed air. The airflow required to drive the cooling blowers, and thus the compressor air bleed, was not known; and the effect of the airflow upon engine performance could not be defined.

for the one-or-a-kind nover plant installation of the test helicopter, no concentrated effort was made toward weight reduction. The gross weight of the emoty test helicopter was 936 pounds heavier than that of a production UH-1B/4R-foot rotor helicopter. This increase in gross weight included flight test instrumentation. The helicopter manufacturer estimated that on a production basis the gross weight of the empty UH-1D/4R-foot rotor helicopter with the XT67 power plant installed would be approximately 160 pounds greater than will the T53-L-11 engine installed.

#### APPENDIX III

#### TEST INSTRUMENTATION

The instrumentation required to measure the following parameters was supplied, calibrated and maintained by the airframe contractor:

# a. Photo Panel

- (1) Record Number
- (2) Pressure Altitude
- (3) Airspeed
- (4) Ambient Temperature
- (5) Collective Stick Position
- (6) Combining Gearbox Oil Pressure
- (7) Cabin Pressure
- (8) Time of Day
- (9) Compressor Inlet Pressure Left and Right Engine
- (10) Engine Torque Left and Right Engine
- (11) Engine Output Shaft Speed Left and Right Engine
- (12) Gas Producer Speed Left and Right Engine
- (13) Total Fuel Used Left and Right Engine

### b. Pilot Panel

- (1) Record Number
- (2) Pressure Altitude
- (3) Airspeed
- (4) Ambient Temperature
- (5) Collective Stick Position

- (6) Rotor Speed
- (7) Compressor Inlet Temperature Left and Right Engine
- (8) Engine Torque Left and Right Engine
- (9) Gas Producer Speed Left and Right Engine
- (10) Power Turbine Inlet Temperature Left and Right Engine
- (11) Total Fuel Used Left and Right Engine
- (12) Fuel Flow Rate Left and Right Engine




PHOTO NO. 5 - INSTRUMENTATION PACKAGE

DOCUMENT CON	TROL DATA - R&I	-	he overall report is classified)
U. S. Army Aviation Test Activity (US. Edwards Air Force Base, California		2ª REPOR	RT SECURITY CLASSIFICATION
Engineering Test of UH-1D Helicopter (	uith XT67 Power	· Plant	Installed
Final Report, 14 October through 22 O  5 AUTHOR(S) (Lest name, little through 30 MELTON, JOHN R., Project Engineer  ANDERSON, WILLIAM A., Project Pilot	ctober 1965		
6 REPORT DATE	74 TOTAL NO OF P	AGES	76. NO OF REFS
April 1966 BA CONTRACT OR GRANT NO	71 9a. ORIGINATOR'S RE	PORT NUM	13 BER(S)
b. PROJECT NO	N/A		
USATECOM Project No. 4-3-0150-17	9b. OTHER REPORT ( this report)	NO(S) (Any	other numbers that may be assigned
d USAAVNTA Project No. 64-20			
U. S. military agencies may obtain copi qual fied users mall request through G command (USAMC) ATTN: AMCPM-IRFO-T. P	es of this repromised the second of the seco	raî Hg Washir	igton, D. C.
11 SUPPLEMENTARY NOTES	U. S. Army Ma (AMCPM-IRFO-T	teriel (	

This report presents the results of limited engineering tests conducted to determine the performance characteristics of the XT67 power plant (i.e. two T72 engines) installed in a YUH-1D/48-foot rotor helicopter. Ten productive hours were flown between 14 Oct 65 and 22 Oct 65. The tests were performed at the airframcontractor's flight test facility located at Greater Southwest Airport, near Fort Worth, Texas. The U. S. Army Avn Test Board (USAAVNTBD) was assigned as Executive Test Agency, responsible for coordinating the test plan preparation, executing the limited serviceability testing and coordinating the test reporting. The U.S. Army Aviation Test Activity (USAAVNTA) was assigned the responsibility for coordinating the planning and reporting of the engineering tests with USAAVNTBDand executing the engineering tests. The XT67 power plant improved the hover and climb performance of the UH-1D/48-foot rotor helicopter by sustaining the helicopter main transmission torque limit to higher altitudes than were possible with the T53-L-11 engine. The XT67 power plant improved the level flight performance by allowing higher cruise speeds for essentially the same range. Increased range could be attained by shutting down one engine. Test installation losses were high but could be reduced significantly through continued development. The static droop characteristics of the XT67 power plant were acceptable. Static load sharing was excellent; however, load sharing during power transient, although adequate, could be improved. The transient response of the power plant-dynamic system was slow. This shortcominshould be corrected prior to service test.

DD FORM 1473

UNCLASSIFIED

Security Classification

Security Classification

14	LIN	KA	LIN	кв	LIN	кс
KEY WORDS	ROLE	WT	ROLE	WT	ROLE	WT
YUH-1D Helicopter XT67 Power Plant Engineering Performance Test Alternate Engine Test						

#### INSTRUCTIONS

- 1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b. GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis in mediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more than one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 7b. NUMBER OF REFERENCES: Enter the total number of references cited in the report.
- 8a. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, &, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).
- 10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those

imposed by security classification, using standard statements such as:

- (1) "Qualified requesters may obtain copies of this report from DDC."
- (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
- (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
- (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

- 11. SUPPLEMENTARY NOTES: Use for additional explanatory notes.
- 12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S), (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Identifiers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is optional.

UNCLASSIFIED

Security Classification